

© Copyright

KE	Y:-
PCOX	INDICATES FAILED PILE CAP (ORIGINAL WORKS 2015/10
SCEOX	EMERGENCY PILE CAP REPAIRS (2016)
CSOX	EMERGENCY PILE CAP REPAIRS (NON STANDARD REPAI
-cvox	EMERGENCY PILE CAP REPAIR VO 1 (2016)
<b>+</b>	► INDICATIVE MAINS WATER FED PUMP
-\$	INDICATIVE SALT WATER FED OUTLET
-\$	► INDICATIVE 2 WAY TUG INLET
	FOR FURTHER DETAILS REFER TO 'ESSEX COUNTY FIRE AND RESCUE SERVICE DRAWING WS/14152

