



<b>RISK ASSESSMENT No.</b>	Removing the Shin Rail around the East end of Southchurch Park Lake	
<b>Establishment:</b>	<b>Assessment by: Jacques Gain</b>	<b>Date: 15/09/2022</b>
<b>Review Date: 15/03/2023</b>	<b>Approved by: Ian Brown</b>	<b>Date: 15/09/22</b>

Hazard / Risk	Who is at Risk?	Initial Risk Rating	Normal Control Measures	Are Control Measures Y/N/NA		Additional Control Measures	Residual Risk Rating
				In Place	Adequate		
Falling into the Lake.  Drowning	<i>Operator, Colleagues Public</i>	med	The original measure was wooden shin rail. This will be removed as it is end of life and deemed a possible safety and trip hazard.  Deploy warning signs of the dangers of going onto the lake if frozen and supervision of children	Yes  Yes	Yes  yes	Installing Sections of two bar Recycled Lumber fencing perpendicular to paths that join the lake path to prevent accidental entry to the water.  Install sections of two bar Recycled lumber fencing to create designated bird feeding stations at evenly spaced points around the east end of the lake.  Installation of two additional life belt stations one either side of the east end of the lake.  Danger shallow water signs to be erected at strategic points all around the lake.  Addition of a sign on the duck feed dispenser that makes people aware of the feeding stations.  Weekly recorded trip hazard and signage inspection of the grass area surround of the lake	low

**REVIEWS:**

<b>DATE OF REVIEW:</b>	<b>REVIEWED BY:</b>	<b>COMMENTS:</b>
<b>DATE OF REVIEW:</b>	<b>REVIEWED BY:</b>	<b>COMMENTS:</b>