

Photo of 1st floor south balcony showing difference in glass obscurity




Photo of 1st floor south east side of balcony showing clear glass on 18/4/18



Photo of both south balconies showing clear glass on 31/3/18



Photo of east side of north balcony showing clear glass and below height on 23/2/18




Photo of west side of north balcony showing clear glass and below height on 23/2/18



View into neighbouring property at No 72 from East side of North balcony