

Southchurch Boulevard - 5 years

No	Area L/A	Reference	Severity	Day	Date	Time	Grid Coords	Link/Node	Street			
1	460	I54531206	Slight	Monday	25/12/2006	00:25	589984/186085					
Location: A13 SOUTHCHURCH ROAD J/W LIFSTAN WAY 1st Rd: A13 2nd Rd: U												
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human -	Phy Fac	Special	Hazard			
30MPH	Single c'way	X-Rds	ATS Dark/lights	l0ther	Wet	None	Ped Phase	None	None			
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age
2	Car	No	Going ahead	E W	On main	Mid junction	No	None		None	Male	30 -
1	Car	No	Right turn	W S	On main	Mid junction	No	None		None	Female	17 -
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped Direction	Ped Movement	Ped location	School Pupil		
1	2	Passenger	Female	28	Slight	Front	Not ped	Not ped	Not ped			
Description: VEH 2 TRAVELLING ALONG SOUTHCHURCH ROAD TOWARDS SOUTHEND.VEH 1 TRAVELLING ALONG SOUTHCHURCH ROAD TOWARDS SHOEBURY.ATS AT JUNCTION WERE GREEN.VEH 1 TURNED RIGHT TOWARDS LIFSTAN WAY INTO THE PATH OF VEH 2 WHERE THEY COLLIDED												
User Information: Contributory Factors: 406V1A 605V1B 607V1B												
2	460	H01110406	Slight	Tuesday	04/04/2006	09:00	589986/186092					
Location: A13 SOUTHCHURCH BOULEVARD J/W LIFSTAN WAY 1st Rd: A13 2nd Rd: U												
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human -	Phy Fac	Special	Hazard			
30MPH	Dual c'way	Multi	ATS Light/with lights	me	Dry	None	Ped Phase	None	None			
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age
2	Car	No	Waiting	E W	On main	Junt appr	No	None		None	Female	39 N
1	Car	No	Going ahead	E W	On main	Junt appr	No	None		None	Male	? N
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped Direction	Ped Movement	Ped location	School Pupil		
1	2	Drv/Rider	Female	39	Slight	No	Not ped	Not ped	Not ped			
Description: VEH 2 SITTING AT TRAFFIC LIGHTS FACING WEST ALONG SOUTHCHURCH BOULEVARD JUNCTION WITH LIFSTAN WAY.VEH 1 TRAVELLING WEST ALONG SOUTHCHURCH BOULEVARD HIT REAR OF VEH 2.BOTH DRIVERS GOT OUT & DRIVER OF VEH 1 ASKED VEH 2 TO MOVE.VEH 1 THEN LEFT SCENE												
User Information: Contributory Factors: 405V1A 602V1B												
3	460	I31980908	Slight	Sunday	07/09/2008	08:30	590100/186109					
Location: SOUTHCHURCH BOULEVARD J/W SOUTHCHURCH RECTORY CHASE 1st Rd: A13 2nd Rd: U												
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human -	Phy Fac	Special	Hazard			
30MPH	Dual c'way	X-Rds	GiveLight/with lights	me	Wet	None	None	None	None			
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age
1	Car	No	Right turn	S W	On main	Mid junction	No	None		None	Male	39 -
2	Car	No	Going ahead	E W	On main	Junt appr	No	None		None	Female	18 -
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped Direction	Ped Movement	Ped location	School Pupil		
1	2	Drv/Rider	Female	18	Slight	No	Not ped	Not ped	Not ped			
Description: VEH 1 HEADING SOUTH ON CASTLETON ROAD INTENDING TO TURN RIGHT (WEST) AT J/W SOUTHCHURCH BOULEVARD.VEH 2 HEADING WEST ON SOUTHCHURCH BOULEVARD.VEH 1 FAILED TO GIVE WAY & HIT OFFSIDE OF VEH 2												
User Information: Contributory Factors: 302V1A 307V1B 401V1B												
4	460	I25850809	Serious	Tuesday	11/08/2009	18:30	590115/186108					
Location: SOUTHCHURCH BVD J/W SOUTHCHURCH RECTORY CRES 1st Rd: A13 2nd Rd:												
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human -	Phy Fac	Special	Hazard			
40MPH	Single c'way	NotJCT	Light/with lights	me	Dry	None	None	None	None			
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age
2	Pedal Cycle	No	Going ahead	E W	On main	Not at	No	None		None	Male	17 N
1	Car	No	Parked	P P	On main	Not at	No	None		None	Female	28 N
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped Direction	Ped Movement	Ped location	School Pupil		
1	2	Drv/Rider	Male	17	Serious	No	Not ped	Not ped	Not ped			
Description: VEH 1 OPEONED CAR DOOR INTHE PATH OF A PEDAL CYCLIST.												
User Information: Contributory Factors: 803V1B												

Southchurch Boulevard - 5 years

No	Area L/A	Reference	Severity	Day	Date	Time	Grid Coords	Link/Node	Street				
5	460	I33151010	Slight	Monday	11/10/2010	20:36	590175/186149						
Location: SOUTHCHURCH BLVD 5YDS EAST OF J/W SACKVILLE RD ON SOUTHEND BOUND TRACK 1st Rd: A13 2nd Rd: U													
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human -	Phy Fac	Special	Hazard				
30MPH	One Way St	Other	GiveDark/lights	lFine	Dry	None	None	None	None				
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age	B
3	Car	No	Parked	P P	On main	Junt appr	No	None		None	Untra.	? N	
2	Car	No	Going ahead	W E	On main	Junt appr	No	None		None	Male	20	-
1	Car	No	Start	W E	On main	Enter main	No	None		None	Female	77	-
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped	Direction	Ped Movement	Ped location	School	Pupil	
1	2	Drv/Rider	Male	20	Slight	No	Not ped		Not ped	Not ped			
Description: VEH 1 WAS PARKED N/S KERB, PULLED OUT INTO THE RD INFRONT OF VEH 2, COLLIDING WITH VEH 2 FRONT THEN COLLIDING WITH VEH 3 TO ITS O/S WHICH WAS PARKED UNATTENDED.													
User Information:													
Contributory Factors: 405V1A													
6	460	H01030306	Slight	Thursday	30/03/2006	08:00	590359/186151						
Location: SOUTHCHURCH BOULEVARD EXIT FROM SOUTHEND HIGH SCHOOL FOR GIRLS 100 M THORPE BAY SIDE (EAST) J/W PILGRIMS CLOSE 1st Rd: A13 2nd Rd:													
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human -	Phy Fac	Special	Hazard				
30MPH	Dual c'way	NotJCT	Light/with lights	lFine	Dry	None	None	None	None				
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age	B
2	Pedal Cycle	No	Going ahead	W E	Footway	Not at	No	None		None	Male	14	N
1	Car	No	Left turn	S W	Footway	Not at	No	None		None	Female	45	-
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped	Direction	Ped Movement	Ped location	School	Pupil	
1	2	Drv/Rider	Male	14	Slight	No	Not ped		Not ped	Not ped	Yes		
Description: VEH 2 BEING RIDDEN ALONG FOOT PATH ON ROUTE TO THORPE BAY SCHOOL VEH 1 BEING DRIVEN AT SLOW SPEED OUT OF EXIT FROM SOUTHEND HIGH SCHOOL FOR GIRLS DRIVER LOOKING TO HER RIGHT TO JOIN OVAL CARRIAGEWAY FAILS TO LOOK TO HER LEFT & STRIKES VHE 2 CAUSING C AS TO BE THROWN OFF LANDING ON FOOTPATH													
User Information:													
Contributory Factors: 405V1A													
7	460	H01000306	Slight	Saturday	18/03/2006	16:15	590616/186243						
Location: A13 SOUTHCHURCH BLVD APPROX 50m EAST J/W WICK CHASE 1st Rd: A13 2nd Rd:													
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human -	Phy Fac	Special	Hazard				
40MPH	Dual c'way	NotJCT	Light/with lights	lFine Wind	Dry	None	None	None	None				
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age	B
1	Car	No	Going ahead	W E	On main	Not at	No	None		None	Male	55	N
2	Pedal Cycle	No	Start	N E	On main	Not at	No	None		None	Male	13	N
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped	Direction	Ped Movement	Ped location	School	Pupil	
1	2	Drv/Rider	Male	13	Slight	No	Not ped		Not ped	Not ped			
Description: VEH 1 TRAVELLING EAST ALONG ROAD IN OFFSIDE LANE.VEH 2 RODE OFF PAVEMENT INTO NEAR SIDE FRONT OF VEH 1													
User Information:													
Contributory Factors: 405V2A 406V2B													
8	460	I32890909	Slight	Sunday	27/09/2009	10:52	590688/186238						
Location: SOUTHCHURCH BOUVELARD APPROX 441.28MTS SOUTHEN SIDE OF J/W ROYAL ARTILLERY WAY SHOEBOURNESS. 1st Rd: A13 2nd Rd:													
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human -	Phy Fac	Special	Hazard				
30MPH	Dual c'way	NotJCT	Dark/lights	notine	Dry	None	Zebra	None	None				
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age	B
2	Car	No	Going ahead	W E	On main	Not at	No	None		None	Female	37	-
1	Car	No	Going ahead	E W	On main	Not at	No	None		None	Male	27	-
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped	Direction	Ped Movement	Ped location	School	Pupil	
1	1	Drv/Rider	Male	27	Slight	No	Not ped		Not ped	Not ped			
Description: PED WAS RUNNING OUT INTO THE CARRIAGEWAY IN AN ATTEMPT TO GET STRUCK BY VEHICLES (POSSIBLE SUICIDE ATTEMPT. VEH 1 STRUCK PED FIRST, PED GOT UP THEN RAN INTO PATH OF VEH 2.													
User Information:													
Contributory Factors: 807C1B 810C1A 999C1B													

Southchurch Boulevard - 5 years

No	Area L/A	Reference	Severity	Day	Date	Time	Grid Coords	Link/Node	Street			
9	460	I01830110	Slight	Monday	25/01/2010	15:20	590711/186271					
Location: SOUTHCHURCH BOULEVARD 148M EATS OF J/W WICK CHASE 1st Rd: A13 2nd Rd:												
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human	- Phy	Fac	Special	Hazard		
30MPH	Single	c'way NotJCT	Light/with	lighter	Wet	None	None	None	None	None		
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age B
1	Car	No	Going ahead	W E	On main	Not at	No	None		None	Male	54 -
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped	Direction	Ped Movement	Ped location	School	Pupil
1	1	Pedestrian	Male	14	Slight	No		North east	Nearside	In c'way		
Description: VEH 1 TRAVELLING EAST TOWARDS SHOEBOURNESS ALONG SOUTHCHURCH. CAS 1 RUN OUT FROM INFONT OF PARKED CAR STRAIGHT INTO PATH OF VEH 1. VEH 1 TRAVELLING SLOW COULDN'T STOP IN TIME AND COLLIDED WITH CAS 1												
User Information: Contributory Factors: 802C1A												
10	460	I12560409	Slight	Wednesday	22/04/2009	08:35	591013/186377					
Location: SOUTCH CHURCH BOULEVARD J/W GLYNDE WAY 1st Rd: A13 2nd Rd: U												
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human	- Phy	Fac	Special	Hazard		
30MPH	Dual	c'way X-Rds	GiveLight/with	light	Dry	None	None	None	None	None		
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age B
2	Car	No	Going ahead	SW NE	On main	Leav main	No	None		None	Male	18 -
1	Car	No	Going ahead	SW NE	On main	Enter main	No	None		None	Female	32 -
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped	Direction	Ped Movement	Ped location	School	Pupil
1	2	Drv/Rider	Male	18	Slight	No		Not ped	Not ped	Not ped		
Description: VEH 1 TRAVELLING ACROSS SHOEBOURNE BOUND CARRIAGEWAY TO GO INTO GLYNDE WAY. VEH 2 TRAVELLING SHOEBOURNE ON SOUTH CHURCH BOULEVARD MOVED INTO LANE 1 PASSING STATIONARY TRAFFIC IN O/S LANE, INTENDING TO TURN LEFT INTO GLYNDE WAY. VEH 1 DIDNT SEE VEH 2 BECAUSE USE OF QUEUE OF TRAFFIC AND COLLIDED WITH VEH 2.												
User Information: Contributory Factors: 405V1B												
11	460	I39571007	Serious	Tuesday	02/10/2007	17:00	591060/186391					
Location: SOUTHCHURCH BOULEVARD APPROX 40m SOUTHEND SIDE OF BOURNES GREEN RAB 1st Rd: A13 2nd Rd: U												
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human	- Phy	Fac	Special	Hazard		
30MPH	Dual	c'way T/Stag	GiveLight/with	light	Dry	None	None	None	None	None		
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age B
2	M/c > 500cc	No	Going ahead	P P	On main	Junt appr	No	None		None	Male	46 -
1	Car	No	Left turn	P P	On main	Junt appr	No	None		None	Male	85 -
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped	Direction	Ped Movement	Ped location	School	Pupil
1	2	Drv/Rider	Male	46	Serious	No		Not ped	Not ped	Not ped		
Description: VEH 2 WAS TRAVELLING ALONG ROAD IN LANE ONE TOWARDS SHOEBOURNE. AS VEH 2 APPROACHED CAR PARK EXIT OF SOUTHWYCKE FLATS, VEH 1 PULLED OUT OF CAR PARK TURNING LEFT ONTO DUAL CARRIAGEWAY. VEH 2 HAD INSUFFICIENT TIME/DISTANCE TO AVOID COLLIDING INTO OFFSIDE FRO NT CORNER OF VEH 1												
User Information: Contributory Factors: 403V1A 405V1A												
12	460	I01550107	Slight	Monday	15/01/2007	08:44	591105/186410					
Location: A13 SOUTHCHURCH BOULEVARD J/W A1159 ROYAL ARTILLERY WAY 1st Rd: A13 2nd Rd: A1159												
Speed	C'Way	Jct Det/Ctrl	Lighting	Weather	Rd Surf	PedX - Human	- Phy	Fac	Special	Hazard		
30MPH	Roundabout	R'dabt	GiveLight/with	light	Wet	None	None	None	None	None		
Veh	Vehicle type	Towing	Manoeuvre	Dir	Veh loc	Junct. loc	Skidding	Hit obj in	Left cway	Hit obj off	Sex	Age B
1	Car	No	Start	W E	On main	Mid junction	No	None		None	Male	31 -
2	M/c <= 50cc	No	Going ahead	S N	On main	Mid junction	No	None		None	Male	53 -
Cas No	Veh ref	Cas Class	Sex	Age	Severity	Car Pass	Ped	Direction	Ped Movement	Ped location	School	Pupil
1	2	Drv/Rider	Male	53	Slight	No		Not ped	Not ped	Not ped		
Description: VEH 2 TRAVELLING AROUND ROUNDABOUT IN THE GENERAL DIRECTION OF ROYAL ARTILLERY WAY. VEH 1 TRAVELLING SOUTHCHURCH BOULEVARD IN THE DIRECTION OF SHOEBOURNE. VEH 1 PULLED ONTO ROUNDABOUT INTO PATH OF VEH 2. VEH 2 COLLIDES WITH OFFSIDE OF VEH 1												
User Information: Contributory Factors: 403V1A 405V1A												