

# 419a Fairfax Drive

Site photos



The unauthorised structure from the front entrance to 419a Fairfax Drive, along Fairfax Drive



Inside of the unauthorised structure



Inside of the unauthorised structure looking towards the front elevation



Inside of the  
unauthorised structure.



Image to show the unauthorised structure is affixed by bolts to the hardstanding.



The unauthorised development and its location in relation to the boundary