



Beaufort Lodge


Locations of Unauthorised UPVC Windows and Door




GROUND FLOOR PLAN



FIRST FLOOR PLAN



ROOF PLAN



FRONT ELEVATION



REAR ELEVATION



EAST ELEVATION



WEST ELEVATION

Photos of UPVC Windows and Door



Photos of Previous Windows

