

Melrose House Photos

24/00136/FUL



Streetscene and street trees

Removal of modern infill and reinstatement of flank detailing and reinstatement of detached form

Reinstatement of traditional windows where lost

Removal of concrete to front and relocation of bins

Improved traditional balustrade



Enhancements

Reinstatement of entrance to No 97

Retained Features

Leaded Windows Original Entrance Feature Tall Chimneys



Eaves Detailing Materials and Decoration



Existing Rear Elevations including extensions and additions




Existing garden building to be converted to cycle store

Relationship with Neighbours (Front)



Relationship with Neighbours



Nursery Covered Play Area

Nursery Open Play Area

Garage block and parking area

Car Park to rear of Jeffreys Court

Landscape buffer to boundary

Relationship with Jeffreys Court to East



Parking Area to rear and main lounge rear outlook

Existing side windows at site and neighbour



Existing side windows on Jeffery Court (Bed 2 and secondary lounge)

Relationship with Day Nursery to West



Existing relationship to covered nursery play area

Existing rear windows and balconies

Stained glass windows to neighbour

Relationship with neighbours to south in Clifftown Parade

